


Если вы видите что-то необычное, просто сообщите мне.

Общая информация

Распиновка

| | | | | |
|------------|----|--|----|----------|
| 3,3V Power | 1 | | 2 | 5V Power |
| BCM 2 | 3 | | 4 | 5V Power |
| BCM 3 | 5 | | 6 | GND |
| BCM 4 | 7 | | 8 | BCM 14 |
| GND | 9 | | 10 | BCM 15 |
| BCM 17 | 11 | | 12 | BCM 18 |
| BCM 27 | 13 | | 14 | GND |
| BCM 22 | 15 | | 16 | BCM 23 |
| 3,3V Power | 17 | | 18 | BCM 24 |
| BCM 10 | 19 | | 20 | GND |
| BCM 9 | 21 | | 22 | BCM 25 |
| BCM 11 | 23 | | 24 | BCM 8 |
| GND | 25 | | 26 | BCM 7 |
| BCM 0 | 27 | | 28 | BCM 1 |
| BCM 5 | 29 | | 30 | GND |
| BCM 6 | 31 | | 32 | BCM 12 |
| BCM 13 | 33 | | 34 | GND |
| BCM 19 | 35 | | 36 | BCM 16 |
| BCM 26 | 37 | | 38 | BCM 20 |
| GND | 39 | | 40 | BCM 21 |

Зарезервированно под HAT Devices (Hardware attached on top), то есть обычные ШИЛДЫ



То что можно использовать для подключения к GPIO

The diagram shows a 40-pin header with the following labels and pin numbers:

| | | | |
|------------|----|----|----------|
| 3,3V Power | 1 | 2 | 5V Power |
| BCM 2 | 3 | 4 | 5V Power |
| BCM 3 | 5 | 6 | GND |
| BCM 4 | 7 | 8 | BCM 14 |
| GND | 9 | 10 | BCM 15 |
| BCM 17 | 11 | 12 | BCM 18 |
| BCM 27 | 13 | 14 | GND |
| BCM 22 | 15 | 16 | BCM 23 |
| 3,3V Power | 17 | 18 | BCM 24 |
| BCM 10 | 19 | 20 | GND |
| BCM 9 | 21 | 22 | BCM 25 |
| BCM 11 | 23 | 24 | BCM 8 |
| GND | 25 | 26 | BCM 7 |
| BCM 0 | 27 | 28 | BCM 1 |
| BCM 5 | 29 | 30 | GND |
| BCM 6 | 31 | 32 | BCM 12 |
| BCM 13 | 33 | 34 | GND |
| BCM 19 | 35 | 36 | BCM 16 |
| BCM 26 | 37 | 38 | BCM 20 |
| GND | 39 | 40 | BCM 21 |

Различные ресурсы

Revision #1

Created 2021-10-23 13:07:02 UTC by gasick

Updated 2023-04-16 19:38:58 UTC by gasick